

CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATION NO:	QC-SLB-25259-19A
LOCATION:	ARTIFICIAL LIFT YARD	JOB NO:	QC-SLB-25259
EXAMINATION DATE:	06/Oct/2025		
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
N/A	05/Mar/2026	BY MANUFACTURE	

Serial Number:	QTY	Description	SWL
SCH-NA-056	01	<u>SKID</u> Dim : 7.97 M(L) X 2.38 M (W) X 3.20 M (H) FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP MOUNTED LIFTING POINTS TARE WEIGHT : 13,550 kg MAX. GROSS WEIGHT : 3550 kg	N/A
Reference Standard:		BS 7072	
Pad Eyes Dimension:		Thickness: 25 mm	Pin Hole: 31 mm
		Length: 160 mm	Height: 115 mm

Is this the first examination after Installation or assembly at a new site or location?	YES		N	O	✓	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	
	S		O				YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	N	O			YES	✓	NO	
	S		O				YES		NO	✓
Identification of any part found to have a defect, which is or could not become a danger to persons, and a description of the defect. NONE										
Is the above a defect, which is of immediate danger to persons?							YES		NO	✓
Is the above a defect, which is not yet but could become a danger to persons?							YES by:			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:										
Particulars of any tests carried out as part of the examination: NONE										
** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory										
** MPI was carried out on the pad eyes Welding Areas and found satisfactory, Check MPI Certificate No :(.....) attached.										
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	✓	NO	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person has examined owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of the Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

