

CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATION NO:		QC-SLB-25249-24A
LOCATION:	WIRE LINE WORKSHOP	JOB NO:		QC-SLB-25249
EXAMINATION DATE:	30/Sep/2025			
LAST INSPECTION	NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE	
19/Mar/2025	29/Mar/2026		BY MANUFACTURE	

Serial Number:	QTY	Description	SWL
L6901010860V01-048	01	<u>GREASE MODULE</u> Dim : 1.46 M(L) X 0.82 M (W) X 1.47 M (H) FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP MOUNTED LIFTING POINTS Tare Weight: 1450 kg Gross Weight: 1450 kg	N/A

Reference Standard:	BS 7072 (UNIT) # 048			
Pad Eyes Dimension:	Thickness:	Pin Hole:	Length:	Height:
	21 mm	17 mm	40 mm	52 mm

Is this the first examination after Installation or assembly at a new site or location?	YE	N	✓	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	✓
	S	O			YES		NO	
If the answer to the above question is YES has the equipment been installed correctly?	YE	✓	N		YES	✓	NO	
	S		O		YES		NO	✓
N/A					YES		NO	✓

Identification of any part found to have a defect, which is or could not become a danger to persons, and a description of the defect. **NONE**

Is the above a defect, which is of immediate danger to persons? YES ☐ NO ☒

Is the above a defect, which is not yet but could become a danger to persons? YES by: _____

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: **NONE**

** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

** MPI was carried out on the pad eyes Welding Areas and found satisfactory, Check MPI Certificate No :(.....) attached.

IS THIS EQUIPMENT SAFE TO OPERATE? YES ☒ NO ☐

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		ASHRAF ELSAAD	

THIS IS TO CERTIFY THAT; a competent person did attend the above mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.