


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB Basra	CERTIFICATION NO:	QC-SLB-25249-28	
LOCATION:	WIRE LINE WORKSHOP			
EXAMINATION DATE:	30/Sep/2025	JOB NO:	QC-SLB-25249	
LAST INSPECTION		NEXT INSPECTION DATE		PROOF LOAD TEST DATE
N/A		29/Mar/2026		BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION			QTY
NV1385B NV1505B NV1112B NV1323B	Safety pin bow Shackles Size: 5/8" Grade: 6 Manufacturer: CROSBY 			04
3.25 TON				
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D UNIT # 048			
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	✓	
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?			
	YES	NO	✓	
	* Within an interval of 12 months?			
	YES	NO	✓	
	* By an examination scheme?			
	YES	NO	✓	
	* After the occurrence of exceptional circumstances?			
	YES	NO	✓	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO	✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	✓	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.