


CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB/25275-42A
LOCATION:	TESTING MBC		
EXAMINATION DATE:	28/Oct/2025	JOB NO:	QC-SLB/25275
LAST INSPECTION	NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
N/A	27/Apr/2026		AFTER ANY REPAIR OR MODIFICATION

Serial Number:	QTY	Description				SWL						
WTAC- C 2062	01	TCP CABIN FULLY WELDED STEEL CONSTRUCTION WITH FOUR TOP-MOUNTED LIFTING POINTS. Dimension: 6 m(L) X 2.41 m (W) X 2.6 m (H) Tare weight: 5600 KG Gross weight: 5600 KG				N/A						
Reference Standard:		BS EN ISO 10855 / DNV 2.7-1										
Pad Eyes Dimension:	Thickness:	Pin Hole:	Length:	Height:								
	40 mm	28 mm	180 mm	90 mm								
Is this the first examination after Installation or assembly at a new site or location?		YES		NO	✓	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months?	YES	✓	NO			
							YES		NO	✓		
If the answer to the above question is YES has the equipment been installed correctly?		YES		✓	NO		In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO		
		N/A				YES			NO	✓		
Identification of any part found to have a defect, which is or could not become a danger to persons, and a description of the defect. NONE												
Is the above a defect, which is of immediate danger to persons?									YES		NO	✓
Is the above a defect, which is not yet but could become a danger to persons?							YES by:					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:												
Particulars of any tests carried out as part of the examination: NONE												
** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory												
** MPI was carried out on the pad eyes Welding Areas and found satisfactory, Check MPI Certificate attached.												
IS THIS EQUIPMENT SAFE TO OPERATE?									YES	✓	NO	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Khalid Mehmood		Mohammed Abdallah	

THIS IS TO CERTIFY THAT; a competent person has examined the owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

