



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25249-45
Location:	WIRELINE PCE WORKSHOP	Job Order No:	QC-SLB-25249
Date of Examination:	30/Sep/2025	Next Inspection Due:	29/Mar/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION										QTY	SWL
NE5040	<u>Four Leg Wire Rope Sling.</u> Diameter: 24 mm Length: 3 (M) IWRC,6 X 36 GAL V MECHANICALLY SPLICEI WITH STEEL FERRULE C/W MASTER LINK ASSEMBLY AT TOP THIMBLE EYE BOTH END SAFETY FACTOR 5:1 										01	8.5 MT @ 0-45°
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008											
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out?							
					* Within an interval of 6 months?		YES	✓	NO			
					* Within an interval of 12 months?		YES		NO	✓		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO		* By an examination scheme?		YES	✓	NO			
					* After the occurrence of exceptional circumstances?		YES		NO	✓		
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None												
Is The Above A Defect Which Is Of Immediate Danger To Persons							YES		NO	✓		
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	✓	YES		By:			
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None												
** Visual And Dimension Check was Carried Out.												
Is This Equipment Safe To Operate?					Yes Accept		✓	NO Reject				

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Alsaad	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.