



LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25245-95
LOCATION:	ARTIFICIAL LIFT		
EXAMINATION DATE:	02/Oct/2025	JOB NO:	QC-SLB-25245
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
N/A	01/Apr/2026	BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION		QTY
L5870 L5867	Safety pin bow Shackles Size: 1-1/8" Grade: 6 Manufacturer: GT Safety Factor: 6:1 		02
			9.5 TON
Applicable Reference Standard:	BS EN 13889 / US FED SPEC RR-C-27 1 D		
* Is this the first examination after installation or assembly at a new site or location? * If the answer to the above question is YES has the equipment been installed correctly?	Was the examination carried out? YES ☒ NO ☒		
	* Within an interval of 6 months? YES ☒ NO ☒		
	* Within an interval of 12 months? YES ☒ NO ☒		
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None			
Is The Above a Defect Which Is of Immediate Danger to Persons			YES ☒ NO ☒
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State The Date By When)			NO ☒ YES ☒ By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual and Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept ☒	NO Reject ☒

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

