



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25292-08
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25292
Date of Examination:	10/NOV/2025	Next Inspection Due:	09/MAY/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION					QTY	SWL				
300910-11	Round 100% Polyester Webbing Sling. Model: RCHPE50 Effective Length: 16 FT Circular Length: 32 FT Manufacturer: Magnum Force SLB Part: T5011077 Safety Factor: 7:1 					01	Vertical 50.000 LBS Choker 40.000 LBS Basket 100.000 LBS				
Applicable Reference Standard:		BS EN 1492-1:2000+A1:2008					TRUCK#5876				
* Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?						
		YES		NO	√	* Within an interval of 6 months?		YES	√	NO	
					* Within an interval of 12 months?		YES		NO	√	
		* If the answer to the above question is YES has the equipment been installed correctly?		YES	√	NO		* By an examination scheme?		YES	√
					* After the occurrence of exceptional circumstances?		YES		NO	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None											
Is The Above A Defect Which Is Of Immediate Danger To Persons							YES		NO	√	
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	√	YES		By:		
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None											
** Visual And Dimension Check was Carried Out.											
Is This Equipment Safe To Operate?					Yes Accept		√	NO Reject			

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
M-Tarek		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

