



Al Takamul Company for Engineering Services
Quality Control – Iraq

LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	SLB BASRA	Certificate no:	QC-SLB-25292-11
Location:	WIRE LINE WORKSHOP	Job Order No:	QC-SLB-25292
Date of Examination:	10/NOV/2025	Next Inspection Due:	09/MAY/2026
Last Inspection		Last Proof Load Test Date	
N/A		BY MANUFACTURE	

IDENTIFICATION NO	DESCRIPTION							QTY	SWL
HST-027963-004	<u>Tie Down Alloy Chain Sling for Login Unit Rig Up</u> Manufacturer: CROSBY SIZE: 3/4’’ X 25 Fit TYPE: CHAIN SLING							01	30,000 LBS
Applicable Reference Standard:	BS EN 818-2:1996+A1:2008							Location: Rig Up Unit 5876	
* Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	* Within an interval of 6 months?	YES	√	NO	
					* Within an interval of 12 months?	YES		NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* By an examination scheme?	YES	√	NO	
					* After the occurrence of exceptional circumstances?	YES		NO	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None									
Is The Above A Defect Which Is Of Immediate Danger To Persons						YES		NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)					NO	√	YES		By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None									
** Visual And Dimension Check was Carried Out.									
Is This Equipment Safe To Operate?					Yes Accept	√	NO Reject		

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
M-Tarek		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

