

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08.Aug.2026	Date of Report:	08.Aug.2026	Certificate No:	QC-B-08-26-183/009
Client Name:	HALLIBURTON	Location:	WPS	Job Number:	QC-B-08-26-183

Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
E8195	01	<u>2 LEGS WIRE ROPE SLING</u> Manufacture: Safety Marine Services Four Legs DIM: 3 FT (L) X 13 MM (DIA) S.O.F: 5:1 IWRC, MECHANICALLY SPLICED WITH STEEL FERRULE C/W MASTER LINK ASSEMBLY HARD EYE BOTH ENDS Location: Attached With Test Pump NO: L-690268 AEME12A036	2.9 TON at 45° Angle	N/A	08.Feb.2026

Reference Standard:	BS EN 13414-1/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1
---------------------	---

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO	✓
				With an interval of 12 months?	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	YES	✓	NO	
				After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE			
Is the above a defect which is of immediate danger to persons:			YES ☐ NO ☒
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
IS THIS EQUIPMENT SAFE TO OPERATE?			YES ☒ NO ☐

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:
ASHRAF ELSAID	MOHAMED ABDALLA	ALI Talib HB48903 Date: 08-AUG-2026 Signature Haliburton
Date of Next Through Examination:	07.Feb.2027	

REV: 01 Dated: 20 June 2022



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of inspection and considered Safe for Lifting.

