Al TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED
Basra, North Rumaila, Quality Control Yard - Iraq
Tel: +9647810009138 / +9647834964657
Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08.Aug.2026	Date of Report:	08.Aug.2026	Certificate No:	QC-B-08-26-183/010
Client Name:	HALLIBURTON	Location:	WPS	Job Number:	QC-B-08-26-183

Last Inspection	Last Proof Load Test Date	Next Proof Load Test Due
08.Feb.2026	28/04/2025	27/04/2027

Serial Number:	QTY	Description
L-690597 V01 AEME 11C041 SAP NO: 11912827	1	**CONTROL PANEL FRAME** DIM: 1.45 M (L) X 0.80 M (W) X 1.47 M (H) FULLY WELDED STEEL STRUCTURE WITH TOP FOUR MOUNTED LIFTING POINTS TARE WEIGHT: 1300 KG M.G.W: 1300 KG

Reference Standard:	BS 7072 / HAL DOC: ST-GL-HAL-HSE-0420

Pad Eyes Dimension:	Thickness:	Pin Hole:	Length:	Height:
	16 MM	18 MM	50 MM	53 MM



Is this the first examination after Installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out: Within an interval of 6 months?	YES	√	NO	
					With an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE

Is the above a defect which is of immediate danger to persons:	YES		NO	√
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)	N/A			

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)
** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory
** MPI was carried out on the pad eyes Welding Areas and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

Name of Inspector:	Name of person authenticating this report:	Client Signature & Stamp:
ASHRAF ELSAID	MOHAMED ABDALLAH	ALI Talib HB48903 Date: 08-AUG-2026 Signature Haliburton
Date of Next Through Examination:	07.Feb.2027	

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.