

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08.Aug.2026	Date of Report:	08.Aug.2026	Certificate No:	QC-B-08-26-183/018
Client Name:	HALLIBURTON	Location:	WPS	Job Number:	QC-B-08-26-183
Last Inspection		Last Proof Load Test Date		Next Proof Load Test Due	
08.Feb.2026		25/02/2024		24/02/2026	
Serial Number:	QTY	Description			
L-690598- MHE036 EQ NO: 11538501	1	BOP FRAME DIM: 1.28 M (L) X 0.30 M (W) X 0.82 M (H) FULLY WELDED STEEL STRUCTURE WITH TOP FOUR MOUNTED LIFTING POINTS TARE WEIGHT: 80 KG PAYLOAD: 440 KG M.G.W: 520 KG			
Reference Standard:		BS 7072/ HAL DOC: WM-GL-HAL-HSE-0420			
Pad Eyes Dimension:	Thickness:	Pin Hole:	Length:	Height:	
	11 MM	20 MM	50 MM	40 MM	
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO		
Was the examination carried out:					
Within an interval of 6 months?		YES	NO	✓	
With an interval of 12 months?		YES	NO	✓	
In accordance with an examination scheme?		YES	NO	✓	
After the occurrence of exceptional circumstances?		YES	NO	✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
** MPI was carried out on the pad eyes Welding Areas and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO
Name of Inspector:	Name of person authenticating this report:	Client Signature & Stamp:			
ASHRAF ELSAID	MOHAMED ABDALLAH	ALI Talib HB48903 Date: 08-AUG-2026 Signature Haliburton			
Date of Next Through Examination:	07.Feb.2027				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

