Al Takamul Company for Engineering Services Quality Control – Iraq

Lifting Appliance Certificate of Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Aberdeen Technical Services	Certificate no:	QC-B-10-26-214/01
Location:	Aberdeen Yard	Job Order No:	QC-B-10-26-214
Date of Examination:	30-10-2026	Next Inspection Due:	29-04-2027
Equipment Serial No:	370523	Last Inspection Date:	10-Oct-2026
S.W.L:	200 Kg		

Description of equipment	Diesel Powered Hydraulically Operated Telescopic Boom Mobile Elevating Work Platform (Man Lift) Manufacturer: TADANO Date of Manufacture: 2017 SPEC: AT-270-2-40410 Model: AT-270 Max. Height: 27 M Max. Radius: 15.4 M Chassis No: NRR35G37000565 Registration No: A 96487 Basra
Ref. Standard	BS EN 280:2013 + A1:2015

Examination Type	Pass	Fail	Notes
Functional Test Operational (No Load)	☑		Elevating Work Platform Found Satisfactory for Further Use.
Load Test (Rated Capacity)	☑		The Elevating Work Platform was found to be acceptable to lift 100 % of the SWL.
Proof Load Test (1.1x Rated Capacity)	---		Proof Load Test Shall Be Done After any Repair/ Modification.

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?			
					Within 6 months?	YES	√	NO
					Within 12 months?	YES		NO	√
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect that is or could become a danger to persons and a description of the defect:
(If none state NONE)
None (The load indicator only displays the operational capacity)

Is the above a defect that is of immediate danger to persons	YES	√	NO	

Is the above a defect that is not yet, but could become a danger to persons: (If YES, state the date by which)

Particulars of any repair, renewal, or alteration required to remedy the defect identified above: None

Particulars of Any Tests Carried Out as Part of The Examination: (If None, State NONE)
In light of the inspection findings, the subject Mobile Elevating Work Platform (MEWP) was visually inspected, operationally tested, and a performance test was conducted, during which no defects were observed. Hence, it was found satisfactory and fit for the intended use.

Is This Equipment Safe to Operate?	Yes, Accept	√	NO Reject	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdalla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioned's work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

Al Takamul Company for Engineering Services Quality Control – Iraq

Lifting Appliance Certificate of Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Services	Location:	ATS Yard	Certificate No:	QC-B-10-26-214-02
Date of Examination:	30-10-2026	Serial No:	370523	Job Number:	QC-B-10-26-214

COMPONENTS	SATISFACTORY	COMMENTS
WHEELS & TYRES	☑ SATISFACTORY	
ANGLE INDICATOR	☑ SATISFACTORY	
BOOM LENGTH INDICATOR	☑ SATISFACTORY	
OPERATING LEVERS & PEDALS	☑ SATISFACTORY	
LIGHT INDICATOR & HORN	☑ SATISFACTORY	
WINDOW WIPERS & MIRROR	☑ SATISFACTORY	
INTEGRITY OF CHASSIS	☑ SATISFACTORY	
OUTRIGGERS & HOUSING	☑ SATISFACTORY	
LEVEL INDICATORS	☑ SATISFACTORY	
LIGHTS & HORN	☑ SATISFACTORY	
HYDRAULIC SYSTEM	☑ SATISFACTORY	
PRIME MOTIVE POWER UNIT	☑ SATISFACTORY	
OPERATOR MANUAL & LOAD CHART	☑ SATISFACTORY	
SAFE LOAD INDICATOR	☑ SATISFACTORY	
PLATEFORM DECK & ACCESS	☑ SATISFACTORY	
AXLES	☑ SATISFACTORY	
BRAKES & CLUTCHES	☑ SATISFACTORY	
STEERING	☑ SATISFACTORY	
BOOM LIFT	☑ SATISFACTORY	
WEAR PADS	☑ SATISFACTORY	
HYDRAULIC HOSES	☑ SATISFACTORY	
BOOM SECTION FOR DAMAGE	☑ SATISFACTORY	
SLEW MOTOR & GEAR	☑ SATISFACTORY	
OIL LEAKAGES OF OPERATION	☑ SATISFACTORY	
BASKET CONDITION	☑ SATISFACTORY	
GENERAL CONDITIONS	☑ SATISFACTORY	
EMERGENCY LOWERING SYSTEM	☑ SATISFACTORY	
EMERGENCY STOP BUTTON	☑ SATISFACTORY	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdalla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioned's work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

Al Takamul Company for Engineering Services Quality Control – Iraq

Lifting Appliance Certificate of Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Services	Location:	ATS Yard	Certificate No:	QC-B-10-26-214-03
Date of Examination:	30-10-2026	Serial No:	370523	Job Number:	QC-B-10-26-214

Test Methods:	Result	COMMENTS
⧫ VT	☑ Accept	
⧫ Functional Test	☑ Accept	
⧫ Performance Test	☑ Accept	
⧫ Proof Load Test {1.1 X SWL}	---	
■ Functional Test		
⧫ Carried out without Load on all functions (including brakes and safety devices) and Controls to check correct and smooth equipment operation, and is free from wear and other damage.		
■ Performance Test		
⧫ Carried out after Functional Test and with the rated load (SWL) applied, where Hoist brakes were found satisfactory.		
■ Proof Load Test		
⧫ Carried out after Performance Test and with the 1.1 x (SWL) applied load, where Hoist brakes were found satisfactory.		

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdalla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioned's work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

Al Takamul Company for Engineering Services Quality Control – Iraq

Lifting Appliance Certificate of Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

PICTORIAL





















LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdalla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioned's work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

Al Takamul Company for Engineering Services Quality Control – Iraq

Lifting Appliance Certificate of Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations







